

Optical Wavelength Laboratories

OPERATIONS GUIDE

PON-2M PON POWER METER

Model Number:
PON-2M



Revision 1.00

OWL-INC.COM

Optical Wavelength Laboratories (OWL)
N9623 West US Hwy 12
Whitewater, WI 53190
Phone: 262-473-0643
Internet: OWL-INC.COM

INTRODUCTION

TABLE OF CONTENTS

SECTION 1: INTRODUCTION

Before You Begin	1
About This Manual	1
Applications.	2
Description	2
Precautions	3
Safety	3
Operational	3
Connector	3
Product Label	3
General Features	4
Display Features.	5

SECTION 2: OPERATION

Power ON/OFF	6
Backlight	6
Battery Status	7
Battery Charging	7

SECTION 3: TEST PROCEDURES

Set Thresholds	8
PASS/FAIL/WARNING Measurement.	9
Optical Power Measurement	10
Set/View Reference..	11
Save/View Stored Data	12

SECTION 4: MAINTENANCE

Replacing the Batteries.	13
Cleaning the Optical Ports	14
Specifications.	15
Maintenance and Calibration Information	15
Contact Information	15

INTRODUCTION

BEFORE YOU BEGIN

All personnel testing optical fibers should be adequately trained in the field of fiber optics before using any fiber optic test equipment.

If the user is not completely familiar with testing fiber optics, they should seek competent training. Such training can be acquired from a variety of sources, such as local hands-on training classes.

Valuable information about fiber optic testing can also be gathered from reading printed literature carefully or by thoroughly reading supplied operations manuals.

Fiber optic testers vary from other types of test equipment due to issues such as:

- 1) standards-based testing
- 2) proper fiber optic test procedures (FOTPs)
- 3) "zeroing" or referencing of power levels
- 4) determining the correct link budget to pass or fail by

Complete understanding of each of these issues is critical for performing proper fiber optic tests.

ABOUT THIS MANUAL

Throughout this manual you will find various symbols that assist with understanding the procedures outlined in this manual. Below is a list of these symbols and a short description of their purpose:



Shows a helpful tip that will make a procedure go more smoothly



Tells the user some useful information about the successful completion of a procedure



Warns the operator of a potentially dangerous condition

INTRODUCTION

APPLICATIONS

Below is a list of test and measurement applications that can be performed using the PON-2M PON (passive optical network) power meter. The procedure for each one of these applications is covered in detail in this manual.

PON Optical Power Measurements. FTTH networks should be measured to ensure that the power levels received from the ONT (optical network terminal) and OLT (optical line terminal) are sufficient for accurate and reliable transmission.

Active Equipment Optical Power Measurements. Active equipment should be measured periodically for correct power levels. The transmitters in this equipment have a known power value. The PON-2M can be directly attached to this equipment via a patch cord to check whether the transmitter is within the manufacturer's specified power range.

Fiber Continuity Testing. Continuity can be measured with the PON-2M by placing a calibrated light source on one end of the fiber and the PON-2M on the other end. This is also a simple way to measure the attenuation of the fiber.

DESCRIPTION

This manual describes the operation of the PON-2M PON power meter.

The PON-2M is a very economical option for measuring the output power of ONT and OLT in FTTx PON networks. The PON-2M is NIST traceable, and is calibrated 1310, 1490, and 1550nm. Up to 10 threshold levels can be set for different measurement points on the FTTH network.

Its user-friendly interface includes nine push-buttons to cover all the functions of the PON-2M. Up to 100 readings can be stored in internal memory, which can be retrieved on the LCD display at a later time.

The PON-2M includes two SC connectors – one for connection to OLT and one for connection to the ONT. An internal pass-through allows for all three FTTx wavelengths to be measured simultaneously when the network is in operation.

The PON-2M is powered by (3) AAA batteries, which allows for 36 hours of battery life.

At additional cost, a model is available that allows data to be downloaded via USB to a PC in Excel spreadsheet format using download software.

INTRODUCTION

PRECAUTIONS


Safety - Exercise caution when working with any optical equipment. High-intensity fiber optic laser sources output potentially dangerous high energy invisible light, and could cause serious, irreparable damage to the eye. Thus, it is recommended to **NEVER** look into the connector port of a light source or the end of a fiber.

Operational - It is important to keep connector ferrules and optical connector ports clean. If dirt, dust, and oil are allowed to build up inside connector ports, irreparable damage may occur to the optics inside the port. For best results, replace dust caps after each use.

Connector - Do NOT insert APC (Angled Physical Contact) connectors into the SC ports on the PON-2M.


PRODUCT LABEL


On the back of each PON-2M PON power meter is a label similar to the one shown below containing model number, serial number, and power requirements.



INTRODUCTION


GENERAL FEATURES



- | | | |
|----|---|---|
| 1 | ONT connector | SC connector; measures upstream signal (1310nm) coming from ONT |
| 2 | OLT connector | SC connector; measures downstream signals (1490 and/or 1550nm) coming from OLT |
| 3 | LCD display | Displays power levels, power units, wavelength, and battery status |
| 4 | ONT status LED | Displays the "Pass/Warning/Fail" status of upstream signal (1310nm) based upon the selected threshold |
| 5 | OLT status LED | Displays the "Pass/Warning/Fail" status of downstream data signal (1490nm) based upon the selected threshold |
| 6 | Video status LED | Displays the "Pass/Warning/Fail" status of downstream video signal (1550nm) based upon the selected threshold |
| 7 | Power button | Press once to power ON or OFF; hold for 2 seconds while power ON to cancel auto shutoff |
| 8 | F/P button | Toggle between "optical power mode" and "Pass/Warning/Fail mode" |
| 9 | Backlight button | Toggle backlight on and off |
| 10 | Units button | Display units in dBm, dB, or μ W |
| 11 | Threshold set button | Set "Pass/Warning/Fail" thresholds; up to 10 thresholds can be set |
| 12 | Save button | Save currently displayed power reading for each wavelength |
| 13 | REF button | Displays optical reference level for each wavelength |
| 14 | USB port | Downloads stored data (for models that support data download) |
| 15 | Charger port | With AC/DC charger, charges batteries |
| |  | DO NOT USE BATTERY CHARGING PORT WITH NON-RECHARGEABLE BATTERIES. THERE IS THE POTENTIAL FOR EXPLOSION AND DAMAGE MAY OCCUR TO THE UNIT AND/OR THE USER. |
| 16 | Battery charger LED | Displays the status of the battery charger |

INTRODUCTION

DISPLAY FEATURES



1	AUTO shut-off status	(blank) = unit will power off automatically; PERM = unit will not power off automatically
2	Data point number	Data point number will appear briefly when storing data point
3	Battery charging status	Appears when unit is plugged into wall power via AC/DC transformer
4	Battery status	Shows remaining battery life
5	ONU 1310nm	Displays power level and measurement unit of 1310nm ONU/ONT output
6	OLT 1490nm	Displays power level and measurement unit of 1490nm OLT output
7	VDO 1550nm	Displays power level and measurement unit of 1550nm VDO (video) output
8	Power level	
9	Measurement units	dBm, dB, or uW

OPERATION

POWER ON/OFF

The **POWER** button serves three purposes:

Power ON with auto-shutoff enabled

Press power button once.

Unit will power off automatically after 10 minutes of inactivity.



Power ON with auto-shutoff disabled

Hold power button for two (2) seconds.

“PERM” will appear in the upper left hand corner of the display. Unit will only power off when pressing the power button again.


Power OFF

Press power button once.




BACKLIGHT

Press the **BACKLIGHT** button to toggle the backlight on or off.







BACKLIGHT OFF




BACKLIGHT ON

OPERATION

BATTERY STATUS

-  Remaining charge: 80 - 100%
-  Remaining charge: 40 - 80%
-  Remaining charge: 20 - 40%
-  Remaining charge: Less than 20%



INSUFFICIENT BATTERY POWER

If battery power is insufficient for operation, the unit will beep and then power off.

BATTERY CHARGING

The PON-2M is powered by (3) AA batteries, but can also operate on wall power when using an approved AC/DC power transformer with the following electrical specifications:



When unit is plugged into a wall outlet via a power transformer and charging the batteries:




the charger icon will appear;



the battery indicator on the display will begin to scroll; and



the battery charger LED will be lit (found on the right side of the unit)



BATTERY CHARGING PRECAUTIONS AND RECOMMENDATIONS



Do **NOT** charge the unit while non-rechargeable batteries are installed. This could cause an unsafe condition that could damage the unit and void the product warranty.



Re-chargeable batteries **MUST** be installed in unit when power transformer is plugged into wall power.



When using re-chargeable batteries, it is recommended to **NOT** charge the device for more than 12 hours at a time.



For maximum battery life of re-chargeable batteries (especially NiCd and NiMH), it is recommended to charge the batteries when the battery indicator shows 20% or less battery life.

TEST PROCEDURES

SET THRESHOLDS

Attaching the PON meter to a different point in the PON network will require a different set of thresholds for power measurements of PON wavelengths. It is important to set thresholds in the PON meter so that it can show PASS/FAIL/WARNING results.

Up to 10 different threshold sets can be configured in the PON -2M PON power meter.

SET THRESHOLDS

Press the **THRESHOLD** button to enter the menu for setting PON thresholds.



DISPLAY

- | | | |
|---|-----------------------------|--|
| 1 | Threshold Set Number | Value: 1 - 10 |
| 2 | Wavelength | 1310, 1490, or 1550nm |
| 3 | Upper FAIL Threshold | Power levels above this value will be reported as FAIL |
| 4 | Warning Threshold | Power levels below this value will be reported as a warning (WRNG) |
| 5 | Lower FAIL Threshold | Power levels below this value will be reported as FAIL |


BUTTONS

- | | | |
|---|-----------------------|---|
| 6 | UP arrow key | Moves cursor to previous menu option

<u>While option is selected:</u>
increases threshold power value |
| 7 | DOWN arrow key | Moves cursor to next menu option

<u>While option is selected:</u>
decreases threshold power value |
| 8 | ENTER key | <u>When Threshold Set Number is highlighted:</u>
toggles through the set numbers

<u>While a threshold power value is highlighted:</u>
moves cursor to next column of threshold power value |



When finished setting thresholds, ensure that the desired threshold set number is selected, then press **THRESHOLD** twice to exit.



After exiting the SET THRESHOLD screen, do NOT change any of the calibration values on the "Calibration" screen that appears. Changing these calibration values will cause the device to lose its NIST calibration.


Press THRESHOLD to exit the "Calibration" screen.

TEST PROCEDURES

PASS/FAIL/WRNG MEASUREMENT

Connecting the PON power meter to the FTTx network

Measures upstream signals coming from customer equipment (ONT: 1310nm)



Measures downstream signals coming from CO/head-end equipment (OLT: 1490 / VDO:1550nm)

Interpreting PASS/FAIL/WRNG results




Before viewing PON power measurements in PASS/FAIL/WRNG mode, ensure the proper threshold values have been set and selected. See the "SET THRESHOLDS" section for more information.



To view results according to the selected threshold, it may be necessary to press the **F/P** button so that the words PASS/FAIL/WRNG appear next to the PON power levels.


- PASS** power level falls between the upper FAIL and Warning threshold levels
- WRNG** power level falls between the Warning and lower FAIL threshold levels
- FAIL** power level is either above the upper FAIL threshold or below the lower FAIL threshold



TEST PROCEDURES




OPTICAL POWER MEASUREMENT


Connecting the PON power meter to the FTTx network



Optical Power Measurement

Optical power can be displayed in dBm, dB, or microwatt (uW) measurement units. Press the **dBm/dB** button to display until the desired measurement unit appears on the display.

-  In Optical Power mode, the PON meter does not compare optical power measurements to any specific threshold.
-  To view results in Optical Power mode, it may be necessary to press the **F/P** button so that PASS/FAIL/WRNG are not displayed, and the indicator LEDs are not lit.
-  To view optical power in dB units, an optical reference must first be set for all wavelengths. See the "SET/VIEW REFERENCE" section for instructions.




TEST PROCEDURES

SET/VIEW REFERENCE

Connecting the PON power meter to the FTTx network

Measures upstream signals coming from customer equipment (ONT: 1310nm)




Measures downstream signals coming from CO/head-end equipment (OLT: 1490 / VDO:1550nm)

Set Reference

To view optical power in dB measurement units, an optical reference must be set for each wavelength.

To set an optical reference, a light source must first be connected for whatever wavelength(s) need to be set. Up to 3 wavelength references can be set simultaneously.

Press and hold the **REF/Enter** button for 2 seconds to set a reference for every wavelength that is currently connected to the PON meter. The display will automatically switch to dB measurement units.



View Reference

Press the **REF/Enter** button once to briefly view the currently set reference levels for each wavelength.

TEST PROCEDURES

SAVE/VIEW STORED DATA


Up to 100 test readings can be stored in the PON-2M PON power meter.

SAVE DATA

Press and hold the **SAVE/RECALL** button to store data for the current fiber under test. The stored reading will include power data for all three wavelengths.



As the data is being saved in memory, the data point number will briefly appear at the top of the display.




RECALL STORED DATA

To view stored data, press the **SAVE/RECALL** button. Five readings will be shown on the display at a time.

Press the **DOWN** button to view the next five readings.

Press the **UP** button to view the previous five readings.



MAINTENANCE

REPLACING THE BATTERIES

The battery compartment is covered by a clip-on plate on the back of the unit. Three (3) AA batteries are required for operation.

Pull back on battery cover locking tab.



Lift off battery cover.



Replace (3) AA batteries.



MAINTENANCE

CLEANING THE OPTICAL PORTS

Required Accessories:

- › Isopropyl alcohol (91% or better)
- › In-adapter fiber optic cleaning accessories, such as 2.5mm cleaning swabs or other in-adapter ferrule connector cleaner.
- › Fiber optic inspection probe (LCD-based, 200x magnification or greater recommended)
- › Compressed Air (optional)

Below are procedures for “wet” cleaning and “dry” cleaning. For best results, a combination of these cleaning methods is recommended.

“WET” CLEAN PROCEDURE

- 1 Wet the tip of a 2.5mm cleaning swab with isopropyl alcohol.
- 2 Carefully insert the wet tip of the swab into the optical port.
- 3 Clean out the optical port according to the directions provided with the swabs.
- 4 Blow dry the optical port with the compressed air. If compressed air is not available, allow 2 minutes for the alcohol to evaporate.
- 5 Inspect the optical port with the fiber optic inspection probe to ensure the port is clear of obstructions.

“DRY” CLEAN PROCEDURE

- 1 Carefully insert a dry 2.5mm cleaning swab or a 2.5mm in-adapter ferrule connector cleaner into the optical port.
- 2 Clean out the optical port according to the directions that came with the cleaning accessories.
- 3 Inspect the optical port with the fiber optic inspection probe to ensure the port is clear of obstructions.

If the port is still dirty, another round of cleaning will be necessary. You may also want to use a combination of “wet” and “dry” cleaning to achieve best results.

If the port is still dirty, another round of cleaning will be necessary. You may also want to use a combination of “wet” and “dry” cleaning to achieve best results.

MAINTENANCE

SPECIFICATIONS

Measurement Range	1310: +10 to -35 dBm 1490: +10 to -50 dBm 1550: +25 to -45 dBm
ORL	35 dB
Pass-through Insertion Loss	< 1.5 dB
Accuracy	±0.5 dB (burst signal) ±0.2 dB
Threshold Sets	10
Data Storage	100
Connectors	SC/PC
Auto Power Off	Yes
Battery Charge	Yes
Operation Time	~36 hours
Storage Temperature	-20 to +60° C
Operating Temperature	-10 to +50° C
Operating/Storage Humidity	90% relative
Power Supply	(3) AAA batteries or AC adapter
Size	7.48" x 3.54" x 1.57"
Weight	~1 pound

MAINTENANCE AND CALIBRATION INFORMATION

Batteries. This unit ships with non-rechargeable alkaline batteries installed. If re-chargeable batteries are required, the user must purchase their own re-chargeable batteries and battery charger.

Storage. When not in use, store the device in a dry, well-ventilated place. Remove the batteries if the device will not be in use for a long period.

Calibration. It is recommended to have Optical Wavelength Laboratories calibrate this unit once per year.

Warranty. The Silicon ZOOM 2 comes standard with a two-year factory warranty, which covers manufacturer defect and workmanship only.

CONTACT INFORMATION

Address:

Optical Wavelength Laboratories, Inc.
N9623 US Hwy 12
Whitewater, WI 53190

Phone:

262-473-0643

Internet:

OWL-INC.COM